

Date: Wednesday, 3/12/2008 1:50:47 PM
 User: Kim Johnston

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : BACK FRAME ASSEMBLY
Job Number : 37870	
Estimate Number : 11129	
P.O. Number :	Part Number : D3017041
This Issue : 3/12/2008 S.O. No. :	Drawing Number : D3017 REV A
Prsht Rev. : NC	Project Number : N/A
First Issue : / / Type : LARGE FAB ASSY	Drawing Revision : A
Previous Run : 36146	Material :
Written By :	Due Date : 4/11/2008 Qty: 1 Um: Each
Checked & Approved By : <u>08 03 12</u>	
Comment : Est. A 01.09.19 New issue EC	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	M4130NT0750W049	4130 Tube .750 OD x.049W
-----	-----------------	--------------------------



Comment: Qty.: 13.1250 f(s)/Unit Total : 13.1250 f(s)
 4130 Tube .750 OD x.049W
 Cut:- AISI 4130N tube, Ø3/4" x 0.049" wall
 Batch: M103012

08/11/03

2.0	M4130NS049	4130 Sheet .049 wall
-----	------------	----------------------



Comment: Qty.: 0.1260 sf(s)/Unit Total : 0.1260 sf(s)
 4130 Sheet .049 wall
 Cut:- AISI 4130N sheet, 18 gauge (0.050 thick)
 Batch: _____

08/11/03

P10 →

3.0	D30177	Lug
-----	--------	-----



Comment: Qty.: 3.0000 Each(s)/Unit Total : 3.0000 Each(s)
 Lug
 Pick:

Qty	Part Number	Description	Batch
3	D3017-7	Lug	<u>B 38567</u>

08/11/03

4.0	LARGE FAB 1	LARGE FABRICATION RESOURCE 1
-----	-------------	------------------------------



Comment: LARGE FABRICATION RESOURCE 1
 1-Cut all tubes as per Dwg D3017
 2-Cut end caps as per Dwg D3017
 3-Weld as per Dwg D3017 using Welding Jig Dt8598
 A/R Steel Rod Batch: M10222C

08/11/03

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
8/11/03	2.0	Δ 3017-11 Qty 2 Batch: B42354 perm. change	MA	08/11/03	3		OSU

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 3/12/2008 1:50:47 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BACK FRAME ASSEMBLY

Job Number: 37870

Part Number: D3017041

Job Number:



Seq. #:

Machine Or Operation:

Description :

4-Drill D3017-041 Using DT8621

5-Deburr

5.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

BE 08/11/04 (1)

6.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

S 08/11/04 (2)

7.0

POWDER COATING

POWDER COATING



M106442



(1X)

Comment: POWDER COATING

Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3

M-1 08/11/05

8.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



11



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

08-11-05 (20)

9.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

PPD 41957

SS 08/11/05 (21)

10.0

QC21

FINAL INSPECTION/W/O RELEASE



08/11/05 (22)

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



MF 08-11-05

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries




DESIGN <i>CP</i>	DRAWN BY <i>CP</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3017	REV. A SHEET 1 OF 2
DATE 01.05.18		TITLE BACK FRAME ASSEMBLY	SCALE 1:1
A	01.05.18	NEW ISSUE	

QTY	PART No.	DESCRIPTION	MATERIAL
X	D3017-041	BACK FRAME ASSEMBLY	N/A
1	D3017-1	TUBE	AISI 4130N TUBE, Ø0.75 DIA x 0.049 WALL (M4130N-T0750W049)
2	D3017-3	TUBE	AISI 4130N TUBE, Ø0.75 DIA x 0.049 WALL (M4130N-T0750W049)
1	D3017-5	TUBE	AISI 4130N TUBE, Ø0.75 DIA x 0.049 WALL (M4130N-T0750W049)
3	D3017-7	LUG	AISI 4130N SHEET, 18 GAUGE (M4130N-S049)
2	D3017-11	END CAP	AISI 4130N SHEET, 18 GAUGE (M4130N-S049)

NOTES


- 1) WELD PER DART QSI 004
- 2) ON SHEET METAL PARTS, BREAK ALL UNMARKED CORNERS 0.020-0.040
- 3) FINISH: POWDER COAT GREY SANDTEX (REF. 4.3.5.6) PER DART QSI 005 4.3
- 4) ALL DIMENSIONS ARE IN INCHES.
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
872
Ø0.37870



Copyright © 2001 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



RELEASED
01-06-07

NO. 57870
WALK ORDER
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
ENGINEERING
RETURN TO
SHOE CO.

D3017-041 BACK FRAME ASSEMBLY
(D3017-1 TUBE, D3017-5 TUBE)

COPYRIGHT © 2001 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL
AND IS SUPPLIED ON THE EXPRESS CONDITION
THAT IT IS NOT TO BE USED FOR ANY PURPOSE
OR COPIED OR COMMUNICATED TO ANY OTHER
PERSON WITHOUT WRITTEN PERMISSION FROM
DART AEROSPACE LTD.

DESIGN	CP	DRAWN BY	CP	DART	DART AEROSPACE LTD. HARRISBURG, ONTARIO, CANADA
CHECKED	A	APPROVED	A	DRAWING NO. D3017	REV. A SHEET 2 OF 2
DATE	01.05.18	TITLE	BACK FRAME ASSEMBLY	SCALE	1:4